CONTROLLED DOCUMENT EG&G - ROCKY FLATS PLANT ENVIRONMENTAL MANAGEMENT This is a RED Stamp

ROCKY FLATS PLANT EMD OPERATING PROCEDURES MANUAL

Manual No.: Procedure No.: 5-21000-OPS-GT Table of Contents, Rev 34

Page:

1 of 3 02/01/93

Effective Date: Organization:

Environmental Management

THIS IS ONE VOLUME OF A SIX VOLUME SET WHICH INCLUDES:

VOLUME I: FIELD OPERATIONS (FO)
VOLUME II: GROUNDWATER (GW)
VOLUME III: GEQTECHNICAL (GT)
VOLUME IV: SURFACE WATER (SW)
VOLUME V: ECOLOGY (EE)
VOLUME VI: AIR (AP)

TABLE OF CONTENTS FOR VOLUME III: GEOTECHNICAL

Procedure <u>No.</u>	<u>Title</u>	Rev. <u>No.</u>	Effective <u>Date</u>
GT.01	Logging Alluvial and Bedrock Material	2	05/12/92
DCN 92.01	Specialized Logging Form	2	11/13/92
DCN 93.01 *DCN 93.02	Logging Logging Deliverables Standard Practices	2 2	01/15/93 01/25/93
GT.02	Drilling and Sampling Using Hollow Stem Auger Techniques	2	05/12/92
DCN 92.01 DCN 92.02 DCN 92.03 DCN 92.04 DCN 92.05	Superseded by DCN 92.03 Superseded by DCN 92.03 Addition of the Drum Characterization Prevention of Down Hole Contamination Field Modification	2 2 2 2 2	07/27/92 07/27/92 07/27/92 08/26/92 12/04/92
*DCN 93.01	Analytical Samples	2	01/25/93
GT.03	Isolating Bedrock from Alluvium with Grouted Surface Casing	2	05/12/92
DCN 92.03	Expired	2	09/03/92
GT.04	Rotary Drilling and Rock Coring	2	05/12/92

£ -,24

DOCUMENT CLASSIFICATION REVIEW WAIVER PER R.B. HOFFMAN, CLASSIFICATION OFFICE JUNE 11, 1991

ROCKY FLATS PLANT EMD OPERATING PROCEDURES MANUAL Manual No.: Procedure No.: Page:

Effective Date: Organization:

5-21000-OPS-GT Table of Contents, Rev 34

2 of 3 02/01/93

Environmental Management

Procedure No.	<u>Title</u>	Rev. No.	Effective <u>Date</u>
GT.05	Plugging and Abandonment of Boreholes	2	05/12/92
DCN 92.01	Field Modification	2	12/09/92
GT.06	Monitoring Wells and Piezometer Installation	2	05/12/92
DCN 92.05 *DCN 92.06	Schematic Diagram Land Fill Methane Wells EXPIRED (replaced with DCN 93.01)	2	06/04/92
DCN 92.07	Provide Consistency	2	12/17/92
DCN 93.01	Borehole Advancement	2	01/04/93
*DCN 93.02	Well Point Installation	2	01/28/93
GT.07	Logging and Sampling of Test Pits and		
	Trenches	2	05/12/92
GT.08	Surface Soil Sampling	2	05/12/92
DCN 92.01	Clarification of Soil Sampling	2	09/03/92
DCN 92.02	Consistency Change	2	10/12/92
DCN 93.01	Work Plan Consistency	2	01/05/93
DCN 93.02	New Section-Surficial Profiling	2	01/15/93
*DCN 93.03	CDH Compliance	2	01/25/93
GT.09	Soil Gas Sampling and Field Analysis	2	05/12/92
GT.10	Borehole Clearing	2	05/12/92
GT.11	Plugging and Abandonment of Wells	2	05/12/92
GT.15	Geophysical Borehole Logging	2	05/12/92
GT.17	Land Surveying	2	05/12/92
GT.18	Surface Geophysical Surveys	2	05/12/92
DCN 92.01	Surface Magnetic Surveys Procedure	2	09/30/92
DCN 92.02	Modification to Stacking Requirements	2	10/15/92
DCN 92.03	Modification to Method of Taking Readings	2	10/15/92
*DCN 93.01	5.4 Field Procedure Revisions	2	01/25/93



ROCKY FLATS PLANT EMD OPERATING PROCEDURES MANUAL

Manual No.: Procedure No.: Page:

5-21000-OPS-GT Table of Contents, Rev 34 3 of 3

02/01/93

Effective Date: Organization:

Environmental Management

Procedure No.	<u>Title</u>	Rev. No.	Effective <u>Date</u>
GT.19	Field Gas Chromatographs	2	05/12/92
GT.20	Procedures for Soil Interstitial Water Sampling and Sampler Installation	2	05/12/92
GT.21	Cone Penetrometer Testing	1	05/12/92
DCN 93.01	CPT Rods	1	01/15/93
GT.24	Approval Process for Construction Activities on or Near Individual Hazardous Substance Sites (IHSSs)	0	05/12/92

CONTROLLED DOCUMENT
EG&G - ROCKY FLATS PLANT
ENVIRONMENTAL MANAGEMENT
This is a RED Stamp

ENVIRONMENTAL MANAGEMENT DOCUMENT CHANGE NOTICE (DCN)

Procedure Number 5-21000-OPS- GT.6, Rev. 2

Page 1 of 3

				·				rageror
Title M e	onitoring	y Wells and Pic	ezometer Inst	allation		Date -81/20/03	DCN Num 5-21000-0	ber 018 PS-93,02
Expires 7 Scope Lin	142819	- · · · · · · · · · · · · · · · · · · ·	ink Number 5	None	vision Required		0	
-					1/28/93			
llem Number	Page	Step or Paragraph		(Use (CN CONTINU	Changes ATION SHEET for Addi	tional Space)	
1	16	5.45 Ded 1/2.8/93	Insert following text as Section 5.4.					
Mo	re cost	•	od than piezo	meters insta	lled by conven DOCUMENT C	ding items Above) Itional drilling LASSIFICATION REVI FMAN, CLASSIFICAT JUNE 11, 1991	IEW WAIVER	~
Concurr	ence	Organization	Req	Date	Concurrence	e Organization	Req	Date
	Imica	QAPM	Х	1/29/93	altomil	ulser User	X	1/28/43
M.C.Bu	ussac	EOM	X	1/28/93	2 Chris	- UBER	X	1/28/93
					D. Sink	EQS	V	1/28/93
Approval	of Respo	nsible Manger	Date	20/23	Is Posting Re	qd? If Yes, By What No upon rec	,	Date Posted

DOCUMENT CHANGE NOTICE (DCN) (Continuation Sheet)

Page 2 of 3 GT-6R2_DCN no. 93-0:

Procedure no. 5-21000-OPS-GT.6, Rev. 2			Title Monitoring Wells and Plezometer Installation	
Scope Limitation Operable Unit Number 5				
ltem Number	Page	Step or Paragraph	Changes (Use DCN CONTINUATION SHEET for Additional Space)	
•	16	5.4	1. Decontaminate the rig and downhole equipment. See SOP FO.3, General Equipment Decontamination, and SOP FO.4, Heavy Equipment Decontamination for specific details regarding decontamination. 2. Set up the rig to obtain a thrust direction as close to vertical as possible. 3. Advance threaded expendable point by either hydraulically pushing or hammering to desired depth. 4. At locations within an IHSS, monitor the breathing zone near the rig for volatile organic compounds. 5. Insert the end of the hand-perforated tubing (Polyethylene or Teflon) with a threaded stud attached into the probe rods. Thread this into the expendable drive point. Length of perforated tubing will range between one and five feet based upon magnitude of anticipated water level fluctuations. 6. Hydraulically withdraw probe rods from hole.	

Justification (Reason for Change - Provide Numbers To Reference Corresponding Items Above)

More cost effective method than piezometers installed by conventional drilling methods for measuring water levels.

856F0028.001

Scope Limitation

Operable Unit Number 8

DOCUMENT CHANGE NOTICE (DCN)

(Continuation Sheet)

Page 3 of 3

67.6, R2 DCN no. 93.02

Procedure no. 5-21000-OPS-QT.6, Rev. 2 Title Monitoring Wells and Plezometer Installation

Changes item Step or Number Page (Use DCN CONTINUATION SHEET for Additional Space) Paragraph 1 5.4 Place 10/20 silica sand 16 filter pack approximately six inches above the top of the screen while keeping tension on the tubing. Place at least six inches of granular bentonite seal above filter pack. Install four-inches long, one-inch diameter PVC casing with threaded or slip cap as protective wellpoint surface casing. Protective casing will be nearly flush with the ground surface. Install four-feet long, three-inch diameter steel post adjacent to protective casing to act as marker and traffic barrier. Post should be installed such that three feet are above ground. Develop well point with peristaltic or inertia pump. Since these well points are only for measuring

water levels, it is not necessary to measure all the parameters referenced in SOP GW.4, Well Development.

11. Survey top of protective casing because well-point tubing is too flexible. Refer to SOP GT.17, Land Surveying, for more information regarding site

Justification (Reason for Change - Provide Numbers To Reference Corresponding items Above)

surveying procedures.

More cost effective method than piezometers installed by conventional drilling methods for measuring water levels.

856F0028.001